



TECHNICAL BULLETIN

May 30, 2025 - RoboteQ discovered an invalid CE mark on the SDC2160 and SDC2160S controller label. Sales records indicate that you have either purchased or have an open order for one or more of these motor controllers.

RoboteQ recommends replacing the current label. Please contact Customer Support at Colton.Simonds@mail.nidec.com with the subject line SDC2 LABELS to request replacement labels, discuss any open orders that require the CE certification or if you have any questions regarding this Technical Bulletin. RoboteQ apologizes for any inconvenience that you may experience. Thank you for your patience and support.

Motor Controller with incorrect label displaying the CE Marking:



Motor Controller with correct label:

